

Inspection Photos

API: 061-06294

Operator: STRACHAN EXPLORATION INC

Inspection Date: 5/26/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06294 | Date: 5/26/2020

Inspection Photos



Photo 1. Facing east along the road used to access the well site. This road is rutting and degraded and needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06294 | Date: 5/26/2020

Inspection Photos



Photo 2. Facing east toward the access road which travels through the cropland. The former road has not been properly decompacted by ripping to 18 inches.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06294 | Date: 5/26/2020

Inspection Photos



Photo 3. The shovel was used to test for soil compaction along the access road and location. The soils were compacted and the shovel was not able to penetrate the surface with pressure.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06294 | Date: 5/26/2020

Inspection Photos



Photo 4. Facing east along the former access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06294 | Date: 5/26/2020

Inspection Photos



Photo 5. Facing east toward the location. All equipment has been removed from the location. The soils at the location are compacted and must be cross ripped to a depth of 18 inches.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06294 | Date: 5/26/2020

Inspection Photos



Photo 6. Photo above was taken outside of the location where soils are not compacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06294 | Date: 5/26/2020