

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/28/2020

Submitted Date:

05/28/2020

Document Number:

696301891

FIELD INSPECTION FORMLoc ID 445579 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96155

Name of Operator: WHITING OIL & GAS CORPORATION

Address: 1700 LINCOLN STREET SUITE 4700

City: DENVER State: CO Zip: 80290

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		WhitingEasternCO@Whiting.com	Eastern Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445581	WELL	DG	05/12/2017		123-43118	Horsetail 30H-1948	DG
445584	WELL	DG	05/02/2017		123-43121	Horsetail 30H-1947	DG
445585	WELL	PR	03/01/2020		123-43122	Horsetail 30H-3116	PR
445586	WELL	PR	04/01/2018		123-43123	Horsetail 30H-1916	PR
445590	WELL	PR	04/01/2018		123-43127	Horsetail 30H-1915	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	All 5 Wellheads are missing Signs		
Corrective Action:	Comply with Rule 210.b.	Date:	08/28/2020

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused Wellhead parts at the 30H-3116 Wellhead, see photos		
Corrective Action:	Comply with 603.f.	Date:	06/29/2020

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 5		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Other	# 5		
Comment:	3 - Gas Lift Injection Wellheads and 2 - TA Wellheads		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:		
Type		

Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 445581 Type: WELL API Number: 123-43118 Status: DG Insp. Status: DG

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: TA Wellhead

Corrective Action: _____ Date: _____

Facility ID: 445584 Type: WELL API Number: 123-43121 Status: DG Insp. Status: DG

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: TA Wellhead

Corrective Action: _____ Date: _____

Facility ID: 445585 Type: WELL API Number: 123-43122 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 445586 Type: WELL API Number: 123-43123 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 445590 Type: WELL API Number: 123-43127 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. All 5 Wellheads are missing the Sign. Unused Wellhead parts at 30H-3116	petrie	05/28/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696301892	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5160741