

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/21/2020

Submitted Date:

05/21/2020

Document Number:

699801142

FIELD INSPECTION FORM

Loc ID 312470 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 9 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|----------------------------|---------|
| Jordan, Reid | | maralextechjr@gmail.com | |
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| Graves, Jim | | mrinc20@maralexinc.com | |
| , BLM | | jbyers@blm.gov | |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 221711 | WELL | PR | 09/01/1995 | GW | 077-08313 | FEDERAL 30-3 | PR |

General Comment:

[COGCC Inspection Report Summary](#)
On Thursday 5/21/20 at approximately 10:30 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC FEDERAL-68S97W /30SWSW, Location #312470 in Mesa County Colorado.
Refer to document #699800782 inspection conducted on 3/25/20. Not all previous corrective actions have been completed. While there, I observed normal production operations.
During this inspection the following possible compliance issues were observed: Access road has not been maintained. See photo #0825 and #1233 with a previous corrective action date of 9/2/19. Debris around equipment and inside pit. See photo #0818, #1234, #0823 and #1236 with a previous corrective action date of 4/1/20. Flow line risers not LO/TO. See photo #0820 and #1237 with a corrective action date of 3/26/20. No pit permit on file. With a previous corrective action date of 4/9/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

| Location | | | |
|--|--|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Access road has not been maintained. See photo #0825 and #1233 | | |
| Corrective Action: | Repair and maintain lease road. | Date: | 09/02/2019 |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | No tank battery on location | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | 911 | | |
| Corrective Action: | | Date: | |
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | Debris around equipment and inside pit. See photo #0818, #1234, #0823 and #1236 | | |
| Corrective Action: | Production facilities, shall be kept free of rubbish. Remove all debris from location. | Date: | 04/01/2020 |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Flow line risers not LO/TO. See photo #0820 and #1237 | | |
| Corrective Action: | Flow line risers not LO/TO or marked are considered unused equipment. Properly lock out and tag out flow line. | Date: | 03/26/2020 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | PIT | | |
| Comment: | Hog panels | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: Horizontal Heated Separator | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |

| | | | |
|--------------------------|-----|-------|--|
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 221711 Type: WELL API Number: 077-08313 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Culverts | | | | |
| Compaction | | | | | | |
| | | Ditches | | | | |
| Ditches | | | | | | |
| Berms | | | | | | |
| | | Compaction | | | | |
| | | Berms | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: No pit permit on record.

Corrective Submit an eForm 15 Pit Report to update COGCC records with current information.

Date: 04/09/2020

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: Mesh Netting Condition: Good

Comment:

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---|
| 402404646 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5157392 |
| 699801143 | Photos for Insp. #699801142 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5157386 |