

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/26/2020

Submitted Date:

05/26/2020

Document Number:

700700776

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
413476 _____ Ramsey, Scott _____ 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 _____ 23 Number of Comments
 _____ 2 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412724	WELL	PR	12/01/2016	OW	045-18563	Savage 41D-8	PR
412725	WELL	PR	12/01/2016	OW	045-18562	Savage 41C-8	PR
412726	WELL	PR	12/01/2016	OW	045-18561	Savage 41B-8	PR
412727	WELL	PR	09/01/2016	OW	045-18560	Savage 41A-8	PR
412728	WELL	PR	12/01/2016	OW	045-18559	Savage 31D-8	PR
412729	WELL	PR	12/01/2016	OW	045-18558	Savage 31C-8	PR
412730	WELL	PR	11/01/2018	OW	045-18557	Savage 31B-8	PR
412731	WELL	PR	09/01/2016	OW	045-18556	Savage 31A-8	PR
412732	WELL	PR	09/01/2016	OW	045-18555	Savage 44D-5	PR
412733	WELL	PR	09/01/2016	OW	045-18554	Savage 44C-5	PR
412734	WELL	PR	09/01/2016	OW	045-18553	Savage 44B-5	PR
412736	WELL	PR	09/01/2016	OW	045-18552	Savage 44A-5	PR
412738	WELL	PR	09/01/2016	OW	045-18551	Savage 34D-5	PR
412740	WELL	PR	09/01/2016	OW	045-18550	Savage 34C-5	PR
412741	WELL	PR	09/01/2016	OW	045-18549	Savage 34B-5	PR
412742	WELL	PR	09/01/2016	OW	045-18548	Savage 34A-5	PR

General Comment:

COGCC Inspection Report Summary

On Tuesday 5/26/20 at approximately 11:00 AM, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus Savage 8A-794, at Location # 413476 in Garfield Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed:

- Random debris around location
- Chemical tank is not labeled

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	one (1) chemical tank near compressor not labeled		
Corrective Action:	label tank	Date:	06/09/2020
Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	_____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Random debris around location		
Corrective Action:	Remove debris	Date:	06/09/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:		corrective date
Type: Compressor	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 16	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 9	
Comment:		
Corrective Action:		Date:
Type: Dehydrator	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 5	
Comment:	chemical tanks	
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Other	#	
Comment:	injection pump/filter pots, dumpsters, porta jons, air compressor	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 16	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	10	400 BBLs	STEEL AST		
Comment: shared containment with condensate tanks and filter pots for injection pump					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	412724	Type:	WELL	API Number:	045-18563	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	412725	Type:	WELL	API Number:	045-18562	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	412726	Type:	WELL	API Number:	045-18561	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	412727	Type:	WELL	API Number:	045-18560	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	412728	Type:	WELL	API Number:	045-18559	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	412729	Type:	WELL	API Number:	045-18558	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	412730	Type:	WELL	API Number:	045-18557	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	412731	Type:	WELL	API Number:	045-18556	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Facility ID: 412732	Type: WELL	API Number: 045-18555	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 412733	Type: WELL	API Number: 045-18554	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 412734	Type: WELL	API Number: 045-18553	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 412736	Type: WELL	API Number: 045-18552	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 412738	Type: WELL	API Number: 045-18551	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 412740	Type: WELL	API Number: 045-18550	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 412741	Type: WELL	API Number: 045-18549	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 412742	Type: WELL	API Number: 045-18548	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches		Culverts				
Berms		Berms				
Gravel		Ditches				
		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402406048	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5159017
700700781	Photos for Savage 8A-794	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5159012