

# Interim Reclamation and Stormwater Inspection

May 29, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 441696

Inspection Document #: 697501591

Weld County, CO

SWNE Section 26 T5N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission


Department of Natural Resources

Inspection Photos  
Location Name: Evans /7-26 Pad  
Location ID: 441696



**Photo 1.** Google Earth aerial imagery taken 9/7/2016 during active drilling operations. Imagery illustrates total disturbance areas associated with drilling operations.

Inspection Photos  
Location Name: Evans /7-26 Pad  
Location ID: 441696



**Photo 2.** Google Earth aerial imagery taken 7/17/2019 after all 22 wells have been on production. Imagery illustrates Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations.

Inspection Photos  
Location Name: Evans /7-26 Pad  
Location ID: 441696



**Photo 3.** Photo taken from the eastern set of wells, facing East. Photo illustrates Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations.

Inspection Photos  
Location Name: Evans /7-26 Pad  
Location ID: 441696



**Photo 4.** Photo taken from the eastern set of wells, facing South. Photo illustrates a stockpile that has been temporarily stabilized with equipment tracking. Operator has attempted to seed into the stockpile with the evidence of drill rows and straw crimped mulch. However, there was little establishment of desirable species and currently has mostly Kochia establishment.

Inspection Photos  
Location Name: Evans /7-26 Pad  
Location ID: 441696



**Photo 5.** Photo taken from the eastern set of wells, facing North. See comments under Photo 4.

Inspection Photos  
Location Name: Evans /7-26 Pad  
Location ID: 441696



**Photo 6.** Photo taken between the two sets of wells, facing South. Photo illustrates Operator has revegetated the interim area including but not limited to the following: smooth brome, crested wheatgrass, intermediate wheatgrass, western wheatgrass, orchard grass, and indian rice grass.

Inspection Photos  
Location Name: Evans /7-26 Pad  
Location ID: 441696



**Photo 7.** Photo taken between the two sets of wells, facing North. See comments under Photo 6.

Inspection Photos  
Location Name: Evans /7-26 Pad  
Location ID: 441696



**Photo 8.** Photo taken from the western set of wells, facing West. Photo illustrates Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations.

Inspection Photos  
Location Name: Evans /7-26 Pad  
Location ID: 441696



**Photo 9.** Photo taken from the western set of wells, facing South. Photo illustrates a stockpile that has been temporarily stabilized with equipment tracking. Operator has attempted to seed into the stockpile with the evidence of drill rows and straw crimped mulch. However, there was little establishment of desirable species and currently has mostly Kochia establishment.

Inspection Photos  
Location Name: Evans /7-26 Pad  
Location ID: 441696



**Photo 10.** Photo taken from the western set of wells, facing North. See comments under Photo 9.

Inspection Photos  
Location Name: Evans /7-26 Pad  
Location ID: 441696



**Photo 11.** Photo taken from the southern location, facing Southeast. Photo illustrates a culvert needing repair. Culvert directs stormwater to a stabilized outlet area (orange arrow).

Inspection Photos  
Location Name: Evans /7-26 Pad  
Location ID: 441696



**Photo 12.** Photo taken from the southern location, facing South. Photo illustrates the outlet of the culvert that directs stormwater to a stabilized outlet area (orange arrow).