

Inspection Photos

Operator: Catamount Energy
API#: 067-09911
Date: 6/1/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with a mix of native and non-native grasses such as crested wheatgrass, smooth brome, and western wheatgrass.



Photo 3. View of the northern project area from the northeastern corner facing westward.

Canada thistles



Photo 4/5. View of Canada thistles observed within the northeastern project area. Approximately 200 individuals observed.



Photos 6/7/8. View of liner debris within the eastern project area.



Photo 9. View of reference area comprised of sagebrush shrubland with an understory of squirreltail, blue grama, and Navajo tea.