

# Inspection Photos

API: 071-07517

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/20/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07517 | Date: 5/20/2020

## Inspection Photos



**Photo 1.** Facing southeast at the beginning of the access road. The cattleguard and road remain with approved variance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07517 | Date: 5/20/2020



## Inspection Photos



**Photo 2.** Facing southeast along the access road. Desirable vegetation is establishing along the road side and the road appears to be stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07517 | Date: 5/20/2020



## Inspection Photos



**Photo 3.** Facing southeast along the access road. There are water bars installed along the road to divert stormwater off the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07517 | Date: 5/20/2020



## Inspection Photos



**Photo 4.** Facing southwest along the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07517 | Date: 5/20/2020



## Inspection Photos



**Photo 5.** Facing south along the access road. Areas of erosion along the road previously observed have been repaired and appear to be stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07517 | Date: 5/20/2020



## Inspection Photos



**Photo 6.** Facing south along the access road. This water bar/berm has been installed along the road which extends out toward the right of the photo. The area to the right is shown in the next photo.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07517 | Date: 5/20/2020



## Inspection Photos



**Photo 7.** Facing northwest toward the reclaimed area and berm which extends out from the road. This area has not adequately re-established vegetation and needs additional seeding.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07517 | Date: 5/20/2020



## Inspection Photos



**Photo 8.** This plant was found in the area of the previous photo and appears to be Diffuse knapweed. Only a few plants were observed which should be controlled before spreading.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07517 | Date: 5/20/2020



## Inspection Photos



**Photo 9.** Facing southwest along the access road ascending toward the location. Water bars are installed along the road. This one can use minor maintenance as signs of stormwater are shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07517 | Date: 5/20/2020



## Inspection Photos



**Photo 10.** Facing southwest along the access road ascending toward the location. Water bars are installed along the road. This one can use minor maintenance as signs of stormwater are shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07517 | Date: 5/20/2020



## Inspection Photos



**Photo 11.** Facing north toward the location. This area has some bare areas which could use touch up hand seeding.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07517 | Date: 5/20/2020



## Inspection Photos



**Photo 12.** Facing south toward the location. The vegetation is establishing well throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07517 | Date: 5/20/2020



## Inspection Photos



**Photo 13.** Facing west toward the fill slope. This area is stabilized with vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07517 | Date: 5/20/2020



## Inspection Photos



**Photo 14.** Facing south toward the location. The vegetation is establishing well throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07517 | Date: 5/20/2020



## Inspection Photos



**Photo 15.** Facing south toward the surrounding undisturbed reference vegetation cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07517 | Date: 5/20/2020