

Inspection Photos

API: 05-071-06094

Operator: AMOCO PRODUCTION COMPANY

Inspection Date: 5/29/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06094 | Date: 5/29/2020

Inspection Photos



Photo 1. Facing east toward the location from across the canyon. Reclamation has not been performed. This photo was taken on 05/29/2020. The following photos were taken during previous inspections.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06094 | Date: 5/29/2020

Inspection Photos



Photo 2. Facing south at the beginning of the access road.

Lat/Long:37.106763,-104.780271



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06094 | Date: 5/29/2020

Inspection Photos



Photo 3. Photo shows erosion along the access road. Access road has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06094 | Date: 5/29/2020

Inspection Photos



Photo 4. Further along the road. Access road has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06094 | Date: 5/29/2020

Inspection Photos



Photo 5. Culvert remains along the road. Erosion is occurring around the outlet.



Inspection Photos



Photo 6. Facing southeast toward the location. The pad has not been recontoured.



Inspection Photos



Photo 7. Facing towards the unstable vertical cut slope. Estimated to be 75' high.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06094 | Date: 5/29/2020

Inspection Photos



Photo 8. Facing down the fill slope shows signs of erosion.



Inspection Photos



Photo 9. Facing toward the fill slope of the location.



Inspection Photos



Photo 10. There is significant signs of erosion off the southeast fill slope.



Inspection Photos



Photo 11. Facing north at the pad.



Inspection Photos



Photo 12. Facing towards the unstable vertical cut slope. Estimated to be 75' high.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06094 | Date: 5/29/2020

Inspection Photos



Photo 13. Facing east toward the location from across the canyon. The fill slope is not stabilized and shows signs of erosion. Location not recontoured. Photo taken 5/29/2020.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06094 | Date: 5/29/2020