

Inspection Photos May 18, 2020  
Location Name: Walden Land Treatment Facility ID: 427373



Location Sign.



Fire lane on the north side of the CE&P facility.

**Inspection Photos May 18, 2020**  
**Location Name: Walden Land Treatment Facility ID: 427373**



**Entrance into cell 1.**



**Dozer in cell 1. All cells recently ripped and turned. Slight hydrocarbon odors noted in soil in cell 1.**



**Inspection Photos May 18, 2020**  
**Location Name: Walden Land Treatment Facility ID: 427373**



**Standing in the NE Corner looking west.**

**Standing in the NE Corner looking north**



**Inspection Photos May 18, 2020**  
**Location Name: Walden Land Treatment Facility ID: 427373**



**Cell 2 looking north.**



**Cell 3 looking north.**

**Inspection Photos May 18, 2020**  
**Location Name: Walden Land Treatment Facility ID: 427373**



**Cell 4 in left of photo looking north.**



**Plastic liner pieces in cell 4.**



**Inspection Photos May 18, 2020**  
**Location Name: Walden Land Treatment Facility ID: 427373**



**Pit liner pieces in cell 4.**



**Berm and fence along west side of cell 4 (looking north).**



**Inspection Photos May 18, 2020**  
**Location Name: Walden Land Treatment Facility ID: 427373**



**Berm buffer land, fence, and fire lane along north side of the facility.**



**Drill cutting management area recently ripped, looking north.**

**Inspection Photos May 18, 2020**  
**Location Name: Walden Land Treatment Facility ID: 427373**



**Drill cutting management area recently ripped, looking north.**



**Western side of drill cutting management area recently ripped, looking north.**



**Inspection Photos May 18, 2020**  
**Location Name: Walden Land Treatment Facility ID: 427373**



**Evidence of wildlife inside of CE&P Facility.**



**Evidence of wildlife inside of CE&P Facility.**