

Inspection Photos
Operator: Catamount Energy
API#: 067-05429
Date: 6/3/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern fill slope from the northeastern corner facing westward. Revegetation is progressing with western wheatgrass, smooth brome, and rubber rabbitbrush.



Photos 3. View of dense Russian knapweeds within the northeastern project area. Review of aerial imagery indicates that the bottom of the fill slope is part of the original project area.



Photos 4. View of musk thistle rosettes within the northeastern project area. Approximately 200 individuals observed.



Photo 5. View of reference area comprised of pinyon and juniper woodland with understory of antelope bitterbrush, big sagebrush, James galleta, and penstemon.