



Photo 1 – View toward the west showing load point and secondary containment in vicinity of produced water tanks and load point.



Photo 2 – View toward the east showing load point and secondary containment in vicinity of produced water tanks and load point.



Photo 3 – Repair of secondary containment wall where pipeline breached containment wall. Patch sealed and secured with screws and then the entire repair area recoated with sealant.