

FORM
6

Rev
02/20

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Replug By Other Operator

Document Number:

402415378

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 16700 Contact Name: Kevin Hejl
 Name of Operator: CHEVRON USA INC Phone: (970) 350-9554
 Address: 100 CHEVRON ROAD Fax: _____
 City: RANGELY State: CO Zip: 81648 Email: kevinhejl@chevron.com

For "Intent" 24 hour notice required, Name: Moran, Rick Tel: (720) 827-6689
COGCC contact: Email: rick.moran@state.co.us

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-103-05553-00
 Well Name: U P R R Well Number: 70-32
 Location: QtrQtr: NENW Section: 32 Township: 2N Range: 102W Meridian: 6
 County: RIO BLANCO Federal, Indian or State Lease Number: _____
 Field Name: RANGELY Field Number: 72370

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.103867 Longitude: -108.871188
 GPS Data: GPS Quality Value: _____ Type of GPS Quality Value: _____ Date of Measurement: _____
 GPS Instrument Operator's Name: _____

Reason for Abandonment: Dry Production Sub-economic Mechanical Problems

Other TEXACO WELL PARTIALLY PLUGGED IN 1954 AND 1961-WELL

Casing to be pulled: Yes No Estimated Depth: _____

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
ENTRADA	3837	3847			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
CONDUCTOR	30	24	48	71				CALC
SURF	17+1/2	16	62.58	520				CALC
1ST	14+3/4	10+3/4	45.5	3,812				CALC
1ST LINER	9	7	23	4,192				CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 3807 with 130 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 59 sks cmt from 520 ft. to 395 ft. Plug Type: CASING Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 570 ft. with 460 sacks. Leave at least 100 ft. in casing 520 CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
 Set 28 sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. _____ inch casing Cut and Cap Date: _____
of
 *Wireline Contractor: _____ *Cementing Contractor: _____
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

Background: UP 70-32 is a Texaco well drilled to 9,360' TD in 1954; it was subsequently P&A'd that same year after being found to be non-productive. The wellbore was re-entered in 1956 to a depth of 4,192', a 7" 23# liner was installed and drilled out to 4,150' PBTD. The Entrada formation was perforated from 3,837'-3,847' and was used for Weber gas storage. There was an unsuccessful attempt to recover the injected gas in 1957 with a flow rate of 1.5 MMCFD and 8.4 BWPD at 1125 to 1430 psi; shut-in wellbore pressure was 1575 psi. An attempt to P&A the well in 1961 was made, but it was not executed. The well was shut-in and abandoned. Plan is to P&A the wellbore to surface.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: ANITA SANFORD
 Title: REGULATORY TECH.ASSISANT Date: _____ Email: ATLX@CHEVRON.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: _____

COA Type	Description

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
402415443	PROPOSED PLUGGING PROCEDURE
402415446	WELLBORE DIAGRAM
402415450	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)