

BP L48 San Juan



V2 Compliance Follow Up Form

18143809714

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200529-18143809714

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

May 29, 2020 3:27:03 PM MDT

222 Farraday Rd, Durango, CO 81303, USA

May 29, 2020 3:24:42 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Apr 28, 2020
Well Name	MAYFIELD GAS UNIT A 2
Location Name (Other)	MAYFIELD GAS UNIT A4
API Number	50670893500
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean up Operator Debris

Photo of first corrective action completed



Completed work description Corrective
 Action 1

Compliance

Photo of second corrective action completed



**Completed work description of corrective
action 2**

Built diversion ditch

Photo of third corrective action completed



**Completed work description of corrective
action 3**

Built rock run downs

Photo of fourth corrective action completed



Completed work description

Erosion repair

Completed work description of corrective action 4

Cleaned up location

Additional photos



Summary of all work completed

Compliance , cleaned out diversion ditch, fixed erosion and installed rock run downs