



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Reflects previous operator. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.e.		Date: 09/10/2020
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Reflects previous operator. See attached photos.		
Corrective Action:	Install sign to comply with Rule 210.e.		Date: 09/10/2020

<b>Emergency Contact Number:</b>			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused automation in wellhead fencing. See attached photo.		
Corrective Action:	Comply with Rule 603.f.		Date: 09/10/2020

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	6' chain link		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	6' chain link		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	6' chain link		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with other tanks.			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	OTHER	STEEL AST		40.389500,-104.810800
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	315 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 245516 Type: WELL API Number: 123-13311 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: TANK BATTERY CONNECTED

Comment: SI

Corrective Action:  Date:

Facility ID: 293731 Type: WELL API Number: 123-26603 Status: PR Insp. Status: PA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder:

Comment: PA; FORM 6(S) DOC#: 402324320 (in process) in well file.

Corrective Action:  Date:

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <span style="border: 1px solid black; padding: 2px;">Erosion to location (south near west ECD). See attached photo.</span>						Date: 09/10/2020
Corrective Action: <span style="border: 1px solid black; padding: 2px; color: red;">Install or repair required BMPs per Rule 1002.f.</span>						
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p style="color: blue;">THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679601367. All corrective actions assigned in previous inspection DOC#: 679601367 have been resolved. Three (3) new corrective actions were observed at the time of re-inspection. Review my inspection, photos and previous inspection DOC#: 679601367 for additional information on this location.</p> <p style="color: blue;">COGCC Inspection Report Summary                      **Weather Conditions: sunny, dry ground                      On Wednesday, June 10, 2020 at approximately 12:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at BARNETT 1-20 (PDC Energy), at location #: 336571 in WELD COUNTY Colorado.                      While there, I observed a shut in facility.                      During this inspection the following possible compliance issues were observed:                      1. Wellhead sign and tank battery sign reflect previous operator. INSTALL SIGN TO COMPLY WITH RULE 210.B. (Corrective Action Date: September 10, 2020) See attached photos #1, 4.                      2. Unused automation inside wellhead fencing. REMOVE AND COMPLY WITH RULE 603.F. (Corrective Action Date: September 10, 2020) See attached photo #2.                      3. Erosion to south end of location (near west separator). Install or repair required BMPs per Rule 1002.f. (Corrective Action Date: September 10, 2020) See attached photo #13.</p> <p style="color: blue;">A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	06/10/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679602852	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5170903">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5170903</a>