

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC  
Facility ID: 476728



**Produced water gathering flowline with 2 temporary patches installed for pressure test**




**Excavation area at 1<sup>st</sup> site. 2<sup>nd</sup> site on top of hill**

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC  
Facility ID: 476728



**Produced water gathering flowline with 2 temporary patches installed for pressure test at 2<sup>nd</sup> excavation site**



**Flowline cut and future pressure test from here to can, plan forward will be made with results of pressure test**

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC  
Facility ID: 476728



**Pinhole found in flowline in the 3 o'clock position**