

FORM  
INSPRev  
X/15State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2020

Submitted Date:

06/10/2020

Document Number:

700401905

## FIELD INSPECTION FORM

 Loc ID: 315246  
 Inspector Name: Moran, Rick  
 On-Site Inspection:   
 2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**
 OGCC Operator Number: 3975  
 Name of Operator: ARGALI EXPLORATION COMPANY  
 Address: PO BOX 416  
 City: RANGELY State: CO Zip: 81648
**Contact Information:**

Contact Name	Phone	Email	Comment
Rector, Brian		brector1983@gmail.com	
Thompson, Bud		BLThomps@BLM.gov	
Rector, Jeff		jbrduco@yahoo.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Blyster, Brandon		blysteroil@aol.com	
, Argali Exploration Company	970-629-1906	argaliexplorationcompany@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230473	WELL	PR	03/01/2019	GW	103-08137	FEDERAL 3-2	PR

**General Comment:**

On 6-9-2020 inspector Rick Moran conducted a follow up inspection at Argali Exploration well Federal 3-2 in Rio Blanco county of FIR documents:

- 1) 679704546 dated 6-19-2019.
- 2) 679704849 dated 7-23-2019.
- 3) 679705093 dated 8-15-2019.
- 4) 679706056 dated 11-12-2019.
- 5) 679706673 dated 12-23-2020.
- 6) 700400359 dated 3-6-2020.
- 7) 700401233 dated 4-24-2020.

The following compliance issues were observed as uncompleted:

- 1) Dead vegetation in pit. Photo 3. Complete by 7-19-2019.
- 2) Unused tank & wood. Photos 2 to 7. Complete by 7-19-2019.
- 3) Chemical container without secondary containment. Photos 8 to 9. Complete by 12-13-2019.

Note: Chemical containers on location need a label and secondary containment. A container without both needs removed from the location.

This is a summary of inspection report 700401905.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pit.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	_____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Vegetation in pit.		
Corrective Action:	Comply with Rule 603.f.	Date:	07/19/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused tank & wood planks next to building.		
Corrective Action:	Comply with Rule 603.f.	Date:	07/19/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PIT		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			
Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 2		
Comment:	Chemical containers.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 230473 Type: WELL API Number: 103-08137 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	

Comment: No secondary containment under chemical container.

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 12/13/2019

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Blowdown      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type:      Liner Condition:

Comment: \_\_\_\_\_  
 Corrective \_\_\_\_\_ Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Wildlife      Fencing Condition: Adequate

Comment: \_\_\_\_\_  
 Corrective \_\_\_\_\_ Date: \_\_\_\_\_

**Netting:**

Netting Type:      Netting Condition:

Comment: \_\_\_\_\_  
 Corrective \_\_\_\_\_ Date: \_\_\_\_\_

Anchor Trench Present:      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment: \_\_\_\_\_  
 Corrective \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700401906	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5171224">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5171224</a>