

# Inspection Photos

API: 05-055-06072

Operator: OXY USA INC

Inspection Date: 6/9/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-055-06072 | Date: 6/9/2020

## Inspection Photos



**Photo 1.** Facing north toward the access road. There is erosion occurring caused by stormwater directed off the road at Lat/Long:37.71484,-105.23178.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06072 | Date: 6/9/2020



## Inspection Photos



**Photo 2.** Facing south toward erosion which is occurring from stormwater runoff shown in previous photo at Lat/Long:37.71484,-105.23178.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06072 | Date: 6/9/2020



## Inspection Photos



**Photo 3.** Facing east on the next switchback of the road. Stormwater is directed off the road which is causing erosion shown in the next photo at Lat/Long:37.71576,-105.23161.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06072 | Date: 6/9/2020



## Inspection Photos



**Photo 4.** Facing nothwest toward erosion which is occurring from stormwater runoff shown in previous photo at Lat/Long:37.71484,-105.23178.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06072 | Date: 6/9/2020



## Inspection Photos



**Photo 5.** There is erosion occurring along the main access road at Lat/Long:37.71665,-105.22713. Red arrow points to 4.5 ft. shovel to depth of erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06072 | Date: 6/9/2020



## Inspection Photos



**Photo 6.** Facing northeast toward the compressor station.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06072 | Date: 6/9/2020

## Inspection Photos



**Photo 7.** Facing northeast toward the SMU 4-4 well. Sign is posted at the wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06072 | Date: 6/9/2020



## Inspection Photos



**Photo 8.** There is a pile of soil and an unused tank stored at the northeast side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06072 | Date: 6/9/2020



## Inspection Photos



**Photo 9.** There is oil stained soils in the soil pile at the northeast side of the location. The soil had an oil odor.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06072 | Date: 6/9/2020



## Inspection Photos



**Photo 10.** There is degraded wood timbers that need to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06072 | Date: 6/9/2020



## Inspection Photos



**Photo 11.** Facing northeast toward the fill slope of the location. The vegetation is well established in the interim reclamation area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06072 | Date: 6/9/2020