

# Inspection Photos

API: 05-055-06314

Operator: OXY USA INC

Inspection Date: 6/9/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 6/9/2020

## Inspection Photos



**Photo 4.** Facing southwest toward the location. Red arrow points to Diffuse knapweed List B noxious weed which needs to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 6/9/2020

## Inspection Photos



**Photo 2.** Facing southeast toward the SMU 4-23 well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 6/9/2020

## Inspection Photos



**Photo 3.** Facing southeast toward the interim reclamation area. Vegetation has not adequately reestablished and there are signs of erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 6/9/2020

## Inspection Photos



**Photo 4.** There is a pile of rock at the south side of the location that needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 6/9/2020

## Inspection Photos



**Photo 5.** There is erosion channels at the reclaimed area at the south side of the location. There are signs that the check dams and wattles have failed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 6/9/2020

## Inspection Photos



**Photo 6.** The wattles at the south side of the location are filled in with sediment and displaced. The BMP's have not been repaired since the previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 6/9/2020

## Inspection Photos



**Photo 7.** Facing east toward the interim reclamation area. Vegetation has not adequately reestablished and there are signs of erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 6/9/2020

## Inspection Photos



**Photo 8.** There are numerous non native Small burnet (*Sanguisorba minor*) plants growing in the interim reclamation area. The plants are not reflective of reference area vegetation and not a desired landowner specie. The plants must be eradicated.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 6/9/2020

## Inspection Photos



**Photo 9.** There is noxious weeds (Mullein) beginning to establish at the west side of the fill slope which needs to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 6/9/2020