

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/05/2020

Submitted Date:

06/05/2020

Document Number:

688800742

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 Hughes, Jim _____ 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10000
 Name of Operator: BP AMERICA PRODUCTION COMPANY
 Address: 1199 MAIN AVENUE SUITE 101
 City: DURANGO State: CO Zip: 81301
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 15 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215294	WELL	PR	02/20/1990	GW	067-06899	HUBERT MORRISON A 1	EI
476772	SPILL OR RELEASE	AC			-	Hubert Morrison A1	EI

General Comment:

On June 5, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #476772, which originated on the Huber Morrison A #1 location. Please refer to document #402412416 for more information regarding this release.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near separator.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Perimeter livestock fencing.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Stock panel fencing and guard fencing.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Orange safety fencing around release area.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Stock panel fencing around separator, telemetry, and meter run.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Domestic gas tap.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas powered.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 215294 Type: WELL API Number: 067-06899 Status: PR Insp. Status: EI

Facility ID: 476772 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 63

Comment: Please refer to Spill/Release Point ID #476772 for more information regarding this release.

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 07/06/2020

Reportable: YES

GPS: Lat 37.217899

Long -107.547925

Proximity to Surface Water: 150

Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Lat

Long

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On June 5, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #476772, which originated on the Huber Morrison A #1 location. Please refer to document #402412416 for more information regarding this release.</p> <p>During this inspection and area was fenced off with orange safety fencing. A 2' by 2' hole was observed within the fencing. Staining, originating from the fenced area, was observed leading into an irrigation channel which, at the time of this inspection, contained flowing water. The channel ultimately terminated in an adjacent field which was being actively irrigated.</p>	hughesjo	06/05/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402414677	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5167768
688800743	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5167762