

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2020

Submitted Date:

06/05/2020

Document Number:

696301909

FIELD INSPECTION FORM

Loc ID 435160 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96155
Name of Operator: WHITING OIL & GAS CORPORATION
Address: 1700 LINCOLN STREET SUITE 4700
City: DENVER State: CO Zip: 80290

Findings:

- 15 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		WhitingEasternCO@Whiting.com	Eastern Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435159	WELL	PR	10/01/2017	OW	123-38484	Razor 26I-2315A	PR
435161	WELL	PR	10/01/2017	OW	123-38485	RAZOR 26I-2313A	PR
435162	WELL	PR	10/01/2017	OW	123-38486	Razor Federal 26I-3513A	PR
435163	WELL	PR	10/01/2017	OW	123-38487	Razor Federal 26I-3514B	PR
435164	WELL	PR	11/26/2014	OW	123-38488	Razor 26I-2316B	PR
435165	WELL	PR	10/01/2017	OW	123-38489	Razor 26I-2314B	PR
448538	WELL	PR	11/01/2017		123-43930	Razor 26I-2347	PR
448539	WELL	PR	10/01/2017		123-43931	Razor Fed 26I-3546	PR
448543	WELL	PR	10/01/2017	OW	123-43935	Razor 26I-2346	PR

General Comment:

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	Razor 261-2314B is missing the Wellhead sign, see photos		
Corrective Action:	Comply with Rule 210.b.	Date:	08/07/2020

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 95%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

	Type	#			corrective date
Type: Bradenhead		# 10			
Comment:	Appear to be plumbed to surface				
Corrective Action:				Date:	
Type: Gas Meter Run		# 10			
Comment:					
Corrective Action:				Date:	
Type: Other		# 10			
Comment:	Gas Lift Injection Wellheads				
Corrective Action:				Date:	

Venting:

Yes/No	<input type="text"/>		
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Flaring:

Type	<input type="text"/>		
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	435159	Type:	WELL	API Number:	123-38484	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	435161	Type:	WELL	API Number:	123-38485	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	435162	Type:	WELL	API Number:	123-38486	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	435163	Type:	WELL	API Number:	123-38487	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	435164	Type:	WELL	API Number:	123-38488	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	435165	Type:	WELL	API Number:	123-38489	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	448538	Type:	WELL	API Number:	123-43930	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	448539	Type:	WELL	API Number:	123-43931	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				

Facility ID: 448543 Type: WELL API Number: 123-43935 Status: PR Insp. Status: PR

Producing Well

Comment: [PR](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Inspection. Razor 26I-2314B is missing the Wellhead sign, see photos	petrie	06/05/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402414136	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5167257
696301910	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5167255