

Inspection Photos
Operator: BP America
API#: 067-06819
Date: 6/11/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing in a grazed condition with grasses such as western wheatgrass and smooth brome.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of musk thistles within the project area, approximately 200 individuals observed.



Photo 5. View of erosional channel approximately 1.5 feet wide and 8 inches deep, near the well pad entrance.



Photo 6. View of reference area comprised of open pinyon juniper woodland with understory of sagebrush, western wheatgrass, and snakeweed.