

Inspection Photos
Operator: BP America
API#: 067-08262
Date: 6/11/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the southeastern fill slope from the eastern corner facing southward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and rubber rabbitbrush.



Photo 3. View of Russian knapweeds within the southeastern project area. Approximately 500 individuals observed.



Photo 4. View of musk thistles along the access road, approximately 200 individuals observed.



Photo 5. View of reference area comprised of pinyon and juniper woodland with understory of western wheatgrass, big sagebrush, rubber rabbitbrush.