

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/04/2020

Submitted Date:

06/06/2020

Document Number:

700401840

**FIELD INSPECTION FORM**
 Loc ID 316688 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10560

Name of Operator: WEST TEXAS OPERATING CO LLC DBA XTREME

Address: PO BOX 2326

City: VICTORIA State: TX Zip: 77902

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Hahn, Mike	361-570-1600 X24	mhahn@xeogc.com	
Thompson, Bud		BLThomps@BLM.gov	
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298910	WELL	PA	11/02/2016	GW	103-11407	HELLS HOLE 18-9	PA

**General Comment:**

COGCC Inspection Report Summary.

On 6-4-2020 inspector Rick Moran conducted a follow up well inspection at Extreme Energy well Hells Hole 18-9 in Rio Blanco county of FIR documents:

- 1) 679704577 dated 6-20-2019.
- 2) 679706659 dated 12-23-2019.

The following compliance issues are uncompleted:

- 1) All equipment on location needs removed. Photos 1 to 5. Complete by 9-23-2019.

Note: A court case was schedule for the Spring 2020 in reference to this lease. District Court, Rio Blanco county, Colorado. Plaintiff: Cap Energy LLC v. Defendant B. P. Allaire. Case No. 2019CV30024 Div: B.

This is a summary of inspection report 700401840.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: No sign present.

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Well is P&A. All equipment on location needs removed.		
Corrective Action:	Comply with Rule 603.f .	Date:	09/23/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	400 BBLs	STEEL AST		,	
Comment:	Tapping on the sides of the tanks implied they are empty.					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		

Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate			Adequate	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**

Facility ID: 298910 Type: WELL API Number: 103-11407 Status: PA Insp. Status: PA

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well was plugged 11-2-2016. Form 6 document 2225543.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402414783	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5167954">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5167954</a>
700401841	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5167943">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5167943</a>