

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/08/2020

Submitted Date:

06/08/2020

Document Number:

699301911

FIELD INSPECTION FORM

Loc ID 438862	Inspector Name: Revas, Robbie	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 26 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 47120 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP Address: P O BOX 173779 City: DENVER State: CO Zip: 80217-				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438861	WELL	PR	01/01/2020	OW	123-40167	SUMMIT 34C-32HZ	PR
438863	WELL	PR	05/02/2015	OW	123-40168	SUMMIT 3N-29HZ	PR
438864	WELL	PR	03/01/2019	OW	123-40169	SUMMIT 28C-29HZ	PR
438865	WELL	PR	04/28/2015	OW	123-40170	SUMMIT 14C-32HZ	PR
438866	WELL	PR	04/20/2015	OW	123-40171	SUMMIT 13C-32HZ	PR
438867	WELL	PR	04/20/2015	OW	123-40172	SUMMIT 3C-29HZ	PR
438868	WELL	PR	01/01/2020	OW	123-40173	SUMMIT 4C-29HZ	PR
438869	WELL	PR	04/27/2015	OW	123-40174	SUMMIT 36C-32HZ	PR
438870	WELL	PR	12/01/2019	OW	123-40175	SUMMIT 29N-29HZ	PR
438871	WELL	PR	01/01/2020	OW	123-40176	SUMMIT 13N-32HZ	PR
438872	WELL	PR	04/21/2015	OW	123-40177	SUMMIT 30N-29HZ	PR
438873	WELL	PR	04/27/2015	OW	123-40178	SUMMIT 36N-32HZ	PR
438874	WELL	PR	04/28/2015	OW	123-40179	SUMMIT 35N-32HZ	PR

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate x 13		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil by the Summit 34C-32HZ WH		
Corrective Action:	Comply with Rule 1002..(2).D	Date:	06/14/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Ag fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Ag fence		
Corrective Action:		Date:	

Equipment:

Type: VRU	# 3		corrective date
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 20		
Comment:	automation, transformers and electric panel.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 13		
Comment:	plumbed to surface and exposed at surface		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 16		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: FWKO	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:		Date:				

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:		shares containment with crude tanks		
Corrective Action:		Date:		

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type		
Comment:		
Corrective Action:	Date:	

Inspected Facilities									
Facility ID:	438861	Type:	WELL	API Number:	123-40167	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	438863	Type:	WELL	API Number:	123-40168	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	438864	Type:	WELL	API Number:	123-40169	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	438865	Type:	WELL	API Number:	123-40170	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	438866	Type:	WELL	API Number:	123-40171	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	438867	Type:	WELL	API Number:	123-40172	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	438868	Type:	WELL	API Number:	123-40173	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	438869	Type:	WELL	API Number:	123-40174	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Facility ID: 438870	Type: WELL	API Number: 123-40175	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 438871	Type: WELL	API Number: 123-40176	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 438872	Type: WELL	API Number: 123-40177	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 438873	Type: WELL	API Number: 123-40178	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 438874	Type: WELL	API Number: 123-40179	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
On Monday 6/08/2020 at approximately 1445 hrs. I, Inspector Robbie Revas,
Conducted an on-site inspection at a Kerr McGee location:

revasr

06/08/2020

Summit 4C-32 HZ at Location #

438862 in Weld County Colorado.

While there, I observed a multi-well wellsite and tank battery.

During this inspection the following possible compliance issues were observed:

1002..(2).D housekeeping: Stained soil by the Summit 34C-32HZ WH CA date 6-14-2020
see photo 14 in location pics. See attached photos.

Location is dry, weather is clear.

A follow up on this site inspection needs to be conducted to ensure the

Compliance issues have been corrected to comply with COGCC rules.

Continuing education COGCC Inspection Report Summary.

This is a summary of inspection report.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402416112	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169147
699301912	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169144
699301913	TB pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169145