

# Inspection Photos

API: 05-055-06105

Operator: OXY USA INC

Inspection Date: 6/9/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06105 | Date: 6/9/2020

## Inspection Photos



**Photo 1.** Facing southeast ascending the hill toward the location. There is erosion occurring along the road. BMP's are needed in this area along the road to prevent further erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06105 | Date: 6/9/2020

## Inspection Photos



**Photo 2.** Facing east overlooking the location. There is unused equipment being stored at the location shown by red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06105 | Date: 6/9/2020

## Inspection Photos



**Photo 3.** Facing toward the well. Sign is posted at the wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06105 | Date: 6/9/2020

## Inspection Photos



**Photo 4.** Facing northwest at the location. There is various unused equipment stored in this area. Since last year during inspection. The amount of unused equipment has increased in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06105 | Date: 6/9/2020