

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2020

Submitted Date:

06/09/2020

Document Number:

689804239**FIELD INSPECTION FORM**Loc ID 316752 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 51922Name of Operator: LYSTER OIL COMPANY INCAddress: 701 COUNTY ROAD 105City: CRAIG State: CO Zip: 81625**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name    | Phone        | Email               | Comment        |
|-----------------|--------------|---------------------|----------------|
| lyster, brandon | 970-326-7533 | blysteroil@aol.com  | owner operator |
| Lyster, Larry   | 970-824-6854 | lysteroil@yahoo.com |                |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name             | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------|
| 232633      | WELL | PR     | 06/12/2006  | OW         | 107-06047 | GRASSY CREEK COAL<br>CO 1 | PR          |

**General Comment:**Routine FIU inspection.

**Location**Overall Good: ☐**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

**Emergency Contact Number:**

Comment: 970-326-8869; 970-326-7533

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | OTHER  |       |            |
| Comment:           | Stained soil at pump jack exhaust, inside shed, and at wellhead.                     |       |            |
| Corrective Action: | Comply with Rule 603.f .<br>Properly dispose of oily waste in accordance with 907.e. | Date: | 06/24/2020 |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

|                          |     |  |       |                 |
|--------------------------|-----|--|-------|-----------------|
| Type: Bird Protectors    | #   |  |       | corrective date |
| Comment:                 |     |  |       |                 |
| Corrective Action:       |     |  | Date: |                 |
| Type: Deadman # & Marked | # 4 |  |       |                 |
| Comment:                 |     |  |       |                 |
| Corrective Action:       |     |  | Date: |                 |
| Type: Pump Jack          | # 1 |  |       |                 |
| Comment:                 |     |  |       |                 |
| Corrective Action:       |     |  | Date: |                 |

**Tanks and Berms:**

|           |   |          |                  |         |        |
|-----------|---|----------|------------------|---------|--------|
| Contents  | # | Capacity | Type             | Tank ID | SE GPS |
| CRUDE OIL | 1 | 300 BBLS | HEATED STEEL AST |         | ,      |
| Comment:  |   |          |                  |         |        |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

|                    |   |          |           |         |        |
|--------------------|---|----------|-----------|---------|--------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
| CRUDE OIL          | 1 | 500 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

Venting:

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

Flaring:

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

| Inspected Facilities |          |       |      |             |           |         |    |               |    |
|----------------------|----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 232633   | Type: | WELL | API Number: | 107-06047 | Status: | PR | Insp. Status: | PR |
| Producing Well       |          |       |      |             |           |         |    |               |    |
| Comment:             | Pumping. |       |      |             |           |         |    |               |    |
| Corrective Action:   |          |       |      | Date:       |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: [Rills on access road. Evidence of sediment being transported both on and off access road.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 06/25/2020

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402416964    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169820">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169820</a> |
| 689804266    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169803">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169803</a> |