

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2020

Submitted Date:

06/09/2020

Document Number:

700300028

FIELD INSPECTION FORMLoc ID 320843 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 9735

Name of Operator: BRAMWELL * RICHARD J & DARLA L

Address: PO BOX 56

City: CHROMO State: CO Zip: 81128

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Costinett, Matthew		matthew.costinett@state.co.us	
Bramwell, Darla		spearu@hughes.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205171	WELL	DM	01/07/1983	GW	007-06047	BRAMWELL 9-D	SI

General Comment:

Follow up inspection for NOAV 401941742.

Well is still shut-in and not producing since COGCC staff performed shut in due to venting flowline on 5/10/2017. Well now has well sign and emergency number and operator contact number. Debris related to old fencing has been removed and well is now fenced with metal panel fencing. Some debris has been removed although some other debris and unused/unserviceable equipment is present.

Domestic use would require Form 44 registration of domestic tap and coordinates of gas delivery point per 1101.c(1) and flowline and tap would be considered new and must meet requirements of 1101.c(2) and (3) for domestic taps and flowlines. Domestic use can only be for the surface owner per 100 series rules.

Well has been documented shut in and not producing for greater than 2 years and requires a mechanical integrity test per Rule 326

Due to age and material of remaining portion of flowline and termination at edge of county road

Location				
Lease Road:				
Type	Access			
comment:	grassy pasture, no distinct road to well			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	OTHER			
Comment:	flowline now marked at county road but no operator name or number per rule 1102g(2). Note: flowline not in use, cut and open ended where routed beneath county road at culvert			
Corrective Action:	Flowline needs to be abandoned and markers can be removed			Date:
Type	WELLHEAD			
Comment:	Well sign now present, ccorrective action satisfactorily completed			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911 for emergency and operator contact number on sign, corrective action completed			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	DEBRIS			
Comment:	Fence debris has been removed. A barrel or portion of barrel was observed near well and appears related.			
Corrective Action:	remove debris per rule 603.f			Date:
Type	WEEDS			
Comment:	well area free of weeds and dead vegetation			
Corrective Action:				Date:
Type	DEBRIS			
Comment:	Unused equipment or tank racks made of wood and fence posts and electrical wires appear related to removed equipment, this material is considered unused equipment or debris and should be removed			
Corrective Action:	remove unused equipment/debris			Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:	flowline connected to domestic separator at well and ends where severed at south side of culvert, the is no surface appearance of flowline from culvert to residence where gas had been used domestically. Due to age, material and integrity issue at culvert, flowline should not be returned to service which would also require pressure testing. Disconnecting flowline would eliminate possibility of it accidently being re-energized with gas.		
Corrective Action:	Disconnect flowline at well. Abandon flowline per 1105		Date:
Type: Ancillary equipment	# 1		
Comment:	wellhead with rods running through bushing		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:	vertical "dryer" tube		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 205171 Type: WELL API Number: 007-06047 Status: DM Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well has not been used for many years, conditions with flowline appear have not changed since 5/10/2017 when venting well was shut in by COGCC staff. With no defined use or way of producing this well could also be considered TA status (temporarily abandoned)

Corrective Action: Perform successful mechanical integrity test per rule 326

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: no erosion/sediment migration off site observed, low area appears to have been filled in

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Gusts Speed: 5-10 (mph) Direction From: w/sw Weather: Partly Temperature: 70 (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHEComment: No FLIR visible gas leaks observed in high sensitivity survey of wellhead, domestic separator, valves and flowline

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402417143	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169936
700300029	well sign and emergency number	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169927
700300030	well head	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169928
700300031	unused equipment/debris	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169929
700300032	debris	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169930
700300033	flowline marker at road	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169931
700300034	flowline entering north end of culvert	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169932
700300035	south end of culvert and no flowline	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169933