

Inspection Photos
Location Name: Robert G Berge #2 Flowline Release
Spill ID 476918



Photo 1 – Spill location adjacent to irrigation ditch




Photo 2 – Partially backfilled spill excavation

Inspection Photos
Location Name: Robert G Berge #2 Flowline Release
Spill ID 476918



Photo 3 – Corrosion visible on piece of flowline removed from the excavation



Photo 4 – Soil berm constructed between spill excavation and irrigation ditch. Boom deployed to help mitigate the additional spread of hydrocarbon fluid into irrigation canal

Inspection Photos
Location Name: Robert G Berge #2 Flowline Release
Spill ID 476918



Photo 5 – Sheen noted on water adjacent to spill location



Photo 6 – Berm placed in irrigation ditch downstream of spill; sheen noted on water caught by boom