

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Unused tank with no labels see pic 4,5		
Corrective Action:	Comply with 603.f	Date:	04/01/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	fabricated fencing around wellhead.		
Corrective Action:		Date:	

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:				Date:	
Type: Vertical Separator	# 1				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:		automation			
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 201466 Type: WELL API Number: 001-06869 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary This is a follow up inspection for document # 687400717 corrective actions from previous inspection are delinquent as of 4/1/2020 On 6/17/2020 at approximately 1039 , I, Inspector Justin Medina conducted an on-site inspection at lke 1-34-1-66 Extraction Oil and Gas, at Loc#319817 in Adams County Colorado. While there, I observed Shut in site During this inspection the following possible compliance issues were observed:Unmarked/unused tank See attached photo #4,5 4/1/2020</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. At time of inspection weather conditions were sunny and windy. This is a summary of inspection report.</p>	medinaj	06/17/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501475	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5177878