

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2020

Submitted Date:

06/17/2020

Document Number:

679602916

**FIELD INSPECTION FORM**Loc ID 449441 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL &amp; GAS INC

Address: 370 17TH STREET SUITE 5300

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

20 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@extracti onog.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449437	WELL	PR	03/01/2019	OW	123-44307	Windsor LV2 2	PR
449438	WELL	PR	01/01/2019	OW	123-44308	Windsor LV2 4	PR
449439	WELL	PR	11/01/2017	LO	123-44309	Windsor LV2 5	PR
449440	WELL	PR	11/01/2017	OW	123-44310	Windsor LV2 7	PR
449442	WELL	PR	03/01/2019	OW	123-44311	Windsor LV2 1	PR
449443	WELL	PR	11/01/2017	OW	123-44312	Windsor LV2 3	PR
449444	WELL	PR	01/01/2019	OW	123-44313	Windsor LV2 6	PR
449445	WELL	PR	11/16/2017	OW	123-44314	Windsor LV2 8	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location. See attached photo		
Corrective Action:	Comply with Rule 603.f.	Date:	09/17/2020
Type	OTHER		
Comment:	Stained soil at two wellheads. See attached photos.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d.	Date:	03/17/2020
Type	OTHER		
Comment:	Stained soil west of location. See attached photo.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d.	Date:	09/17/2020
Type	TRASH		
Comment:	Trash near gas meters. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	04/10/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date	
Type: Bradenhead	# 8				
Comment:					
Corrective Action:				Date:	
Type: Compressor	# 4				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 8				
Comment:					
Corrective Action:				Date:	
Type: Emission Control Device	# 3				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 8				
Comment:					
Corrective Action:				Date:	
Type: Vertical Separator	# 1				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 2				
Comment:					
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLS	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:	Shares containment with other tanks.					
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	<50 BBLS	BV CONCRETE		,	
Comment:						

Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Metal	Adequate		Walls Sufficent		Base Sufficent		Adequate
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type		Tank ID	SE GPS	
CONDENSATE	2	OTHER	BV CONCRETE			,	
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity) 60 BBLs							
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Comment: Shares containment with other tanks.							
Corrective Action:						Date:	
Contents	#	Capacity	Type		Tank ID	SE GPS	
CRUDE OIL	8	300 BBLs	STEEL AST			,	
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Metal	Adequate		Walls Sufficent		Base Sufficent		Adequate
Comment:							
Corrective Action:						Date:	
<u>Venting:</u>							

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities									
Facility ID:	449437	Type:	WELL	API Number:	123-44307	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	449438	Type:	WELL	API Number:	123-44308	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	449439	Type:	WELL	API Number:	123-44309	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	449440	Type:	WELL	API Number:	123-44310	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	449442	Type:	WELL	API Number:	123-44311	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	449443	Type:	WELL	API Number:	123-44312	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	449444	Type:	WELL	API Number:	123-44313	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	449445	Type:	WELL	API Number:	123-44314	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679602488. All corrective actions assigned in previous inspection DOC#: 679602488 have not been resolved. Corrective actions have been re-assigned to location with original corrective action date. Two (2) new corrective actions were observed at the time of re-inspection.</p> <p>COGCC Inspection Report Summary  **Weather Conditions: sunny, dry ground  On Wednesday, June 17, 2020 at approximately 12:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at WINDSOR LV2 14-M PAD (Extraction Oil &amp; Gas), at location #: 449441 in WELD COUNTY Colorado.  While there, I observed a producing facility.  During this inspection the following possible compliance issues were observed:  1. Stained soil at two wellheads. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per RULE 1002.F.(2).D. (Corrective Action Date: March 17, 2020) See attached photos #10, 13.  2. Stained soil east of location. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per RULE 1002.F.(2).D. (Corrective Action Date: September 17, 2020) See attached photo #4.  3. Unused riser (east of location) Operator must LO/TO riser within 24 hrs, if no future use, operator must remove per Rule 603.f. (Corrective Action Date: September 17, 2020) See attached photo #4.  4. Trash and/or unused equipment at gas meters. Remove and comply with Rule 603.f. (Corrective Action Date: April 10, 2020) See attached photo #7.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  This is a summary of inspection report.</p>	santistb	06/17/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679602917	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5178181">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5178181</a>