

Inspection Photos
Operator: BP America
API: 067-08955
Date: 6/16/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing in portions but remains sparse in other portions. Slopes are not yet stabilized with desirable vegetation. Species observed include: western wheatgrass, intermediate wheatgrass, and smooth brome.



Photo 3. View of BMPs within the eastern project area that need maintenance. Wattles are no longer staked and filled with sediment, cobble run-down is filling with sediment.



Photo 4. View of the reference area, comprised of pinyon and juniper woodland with understory of grasses and forbs such as western wheatgrass, blue grama, prickly pear, as well as shrubby gambel oak.