

Inspection Photos
Operator: BP America
API: 067-06639
Date: 6/16/2020



Photo 1. View of the reclaimed access road from the beginning of access, facing north, toward the project area. Reclamation appears to be progressing, with perennial grasses becoming established.



Photo 2. View of the western well pad from the southwestern corner facing northward. Revegetation is progressing in an early seral condition. Continued monitoring is needed to ensure successful establishment.



Photo 3. View of the reclaimed project area from the southwestern edge facing center. Drainage patterns are recontoured within the project area, and appear to be functioning at this time.



Photo 4. Birdseye view of young perennial grasses, straw mulch, and yellow sweet clover. Native forbs such as sagebrush also observed. Typical of revegetation condition within the project area.



Photo 5. View of dense Russian knapweeds within the eastern project area. Knapweed infestation needs to be controlled as it is threatening desirable revegetation.



Photo 6. View of musk thistles within the western project area. Approximately 75 individuals observed.



Photo 7. View of the reference area, comprised of pinyon and juniper woodland with understory of sagebrush, antelope bitterbrush, Indian ricegrass, prickly pear, penstemon, etc.