

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/11/2020

Submitted Date:

06/15/2020

Document Number:

687400805

**FIELD INSPECTION FORM**
 Loc ID 449174 Inspector Name: Huck, Keith On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10110

Name of Operator: GREAT WESTERN OPERATING COMPANY LLC

Address: 1001 17TH STREET #2000

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449155	WELL	PR	07/01/2018		001-09984	Ocho LD 17-372HN	PR
449158	WELL	PR	06/01/2018		001-09987	Ocho LD 17-370HN	PR
449164	WELL	PR	12/01/2017		001-09993	Ocho LD 17-367HC	PR
449165	WELL	PR	10/01/2018		001-09994	Ocho LD 17-367HN	PR
449166	WELL	PR	08/01/2018		001-09995	Ocho LD 17-362HC	PR
449167	WELL	PR	08/01/2018		001-09996	Ocho LD 17-364HC	PR
449168	WELL	PR	06/01/2018		001-09997	Ocho LD 17-368HN	PR
449169	WELL	PR	07/01/2018		001-09998	Ocho LD 17-369HN	PR
449170	WELL	PR	07/01/2018		001-09999	Ocho LD 17-364HN	PR
449171	WELL	PR	07/01/2018		001-10000	Ocho LD 17-369HC	PR
449172	WELL	PR	06/01/2017		001-10001	Ocho LD 17-365HN	PR
449173	WELL	PR	07/01/2018		001-10002	Ocho LD 17-363HN	PR

**General Comment:**

### Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	All are good except. Ocho LD17-364HN well sign is missing. The Ocho LD17-364HC sign is on this well needs to be moved over to the correct well. See attached pictures		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	08/11/2020

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Cattle fencing around all wellheads		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 2		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 2		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 15		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	ECO Vapor Recovery Unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Automation RTU's		
Corrective Action:		Date:	
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 12		
Comment:	All appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: VRU	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	533BBLs	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berm with production tank			

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	9	OTHER	STEEL AST		39.982903,-104.913164	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	533BBLs	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: <u>449155</u>	Type: <u>WELL</u>	API Number: <u>001-09984</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449158</u>	Type: <u>WELL</u>	API Number: <u>001-09987</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449164</u>	Type: <u>WELL</u>	API Number: <u>001-09993</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449165</u>	Type: <u>WELL</u>	API Number: <u>001-09994</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449166</u>	Type: <u>WELL</u>	API Number: <u>001-09995</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449167</u>	Type: <u>WELL</u>	API Number: <u>001-09996</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449168</u>	Type: <u>WELL</u>	API Number: <u>001-09997</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449169</u>	Type: <u>WELL</u>	API Number: <u>001-09998</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449170</u>	Type: <u>WELL</u>	API Number: <u>001-09999</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449171</u>	Type: <u>WELL</u>	API Number: <u>001-10000</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449172</u>	Type: <u>WELL</u>	API Number: <u>001-10001</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>449173</u>	Type: <u>WELL</u>	API Number: <u>001-10002</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

**Producing Well**

Comment: <u>PR</u>	
Corrective Action: <u></u>	Date: <u></u>

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On (Thursday) (06/14/2020) at approximately (8:15), I, Inspector (Keith Huck), Conducted an on-site inspection at (Ocho LD Pad) (Great Western), at (Location#449174) in (Adams,County) Colorado.</p> <p>While there, I observed a (Production Facility.)</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Wellhead signs. Ocho LD17-364HN well sign is missing. The Ocho LD17-364HC sign is on the wrong well. Sign needs to be moved over to the correct well. See attached pictures.</p> <p>Install sign to comply with Rule 210.b. Corrective Action Date 8/11/2020</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	huckk	06/12/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402422151	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5174707">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5174707</a>
687400808	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5174696">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5174696</a>