

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/03/2020

Submitted Date:

06/11/2020

Document Number:

697600937**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453728	SPILL OR RELEASE	CL			-	Segal 42-24	EI
453778	TANK BATTERY	AC	01/18/2018		-	Segal Battery	EI

General Comment:

spill 453728 and battery 453778 inspected during process of removal of partly buried produced water vessel
Spill is closed based an assumption of adequate site investigation and remeidation efforts as documented in approved Form 27 process
(Project 10922)

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		
Comment: vessel being removed as shown in attached photo under approved plan in site investigation and remediation plan (10922) Condition of approval for reporting in form 27 approved prior to removal is below. Operator provided 24 hour prior notice of removal of PBV as requested.					
Corrective Action: Submit supplemental form 27 to provide details of site investigation including site map, analytical summary including field screening data and analytical reports within 45 days following removal of produced water vessel.					Date: 07/20/2020

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 453728	Type: SPILL OR	API Number: -	Status: CL	Insp. Status: EI
---------------------	----------------	---------------	------------	------------------

Facility ID: 453778	Type: TANK	API Number: -	Status: AC	Insp. Status: EI
---------------------	------------	---------------	------------	------------------

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402422643	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5175312
697600938	partly buried vessel following removal from ground	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5175306
697600939	hydrocarbon stained soils in excavation of PBV	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5175307