

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2020

Submitted Date:

06/22/2020

Document Number:

700900166**FIELD INSPECTION FORM**Loc ID 428424 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 19035

Name of Operator: OVERLAND RESOURCES LLC

Address: SUITE C18 PMB 440

City: GREENWOOD State: CO Zip: 80121

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

17 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pandolfo, Chris	630-387-6506	admin@overlandresourcesllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428427	WELL	SI	07/01/2017	OW	001-09744	Handke 3	SI
428439	WELL	SI	07/01/2017	OW	001-09745	Handke 4	SI

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Main		
comment:	Adequate		
Corrective Action	L	Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds.		
Corrective Action:	Location is within a designated setback location, remove Weeds per Rule 603 f. Corrective Action Date 7/6/2020. See attached photos #1 through 10.		Date: 07/06/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Pump Jack	# 1		corrective date
Comment:	Inadequate berms around chemical tanks tank(s).		
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4). Inadequate berms around tank(s) Corrective action Date 7/13/2020 See attached photo #4.		
Type: Gas Meter Run	# 1		Date: 07/13/2020

Comment:		Date:	
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:		Date:	
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:	Stained soil under separator,	Date:	
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Corrective action date 7/20/2020. See attached photos #5 through #10.	Date:	07/20/2020
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface	Date:	
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:		Date:	
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 bbls	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berm with Crude tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		

Other (Capacity) 75 bbls						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient		Base Sufficient	Adequate	
Comment: Shares berm with Crude tanks.						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	6	300 BBLS	STEEL AST		39.800463,-104.527385	
Comment: Stained soil under separator, several around Crude tanks and around load off bucket. Bull plug missing from loadoff line.						
Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Corrective action date 7/20/2020. See attached photos #5 through #10. Location is within a designated setback location, bullplug or cap all loadlines per Rule #604.c.(2)O. Corrective action Date 6/29/2020. See attached photos #9 & 10.						Date: 07/20/2020
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient		Base Sufficient	Adequate	
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No						
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**

Facility ID: 428427 Type: WELL API Number: 001-09744 Status: SI Insp. Status: SI

Facility ID: 428439 Type: WELL API Number: 001-09745 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Appears to be plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday June 17, 2020 approximately 9:30am, I, Inspector Chane Finkenbinder, Conducted an on-site inspection at Handke 4, OverLand Resources, at API # 001-09745 in Adams County Colorado.</p> <p>While there, I observed a Shut in well,</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil under separator, several around Crude tanks and around load off bucket.</p> <p>Control and contain spills/releases and clean up per Rule 906.a. Corrective action date 7/20/2020. See attached photos #5 through #10.</p> <p>Bull plug missing from loadoff line. Location is within a designated setback location, bullplug or cap all loadlines per Rule #604.c.(2)O. Corrective action Date 6/29/2020. See attached photos #9 &amp; 10.</p> <p>Inadequate berms around chemical tanks tank(s),</p> <p>Repair or install berms or other secondary containment devices per Rule 605.a.(4).</p> <p>Inadequate berms around tank(s) Corrective action Date 7/13/2020 See attached photo #4.</p> <p>Weeds. Location is within a designated setback location, remove Weeds per Rule 603 f. Corrective Action Date 7/6/2020. See attached photos #1 through 10.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	06/22/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900167	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5180808">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5180808</a>