

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/22/2020

Submitted Date:

06/22/2020

Document Number:

697600962**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knop, Max	303-825-4822	MKnop@kpk.com	
Binschus, Chris		chris.binschus@state.co.us	
,		cogcc@kpk.com	
MacLaren, Joe		joe.maclaren@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476987	SPILL OR RELEASE	AC	06/22/2020		-	NESSSU CONSOLIDATION	EI

**General Comment:**

flowline related spill reported as discovered on 20June2020

at approximate location of flowline spill 470915 with site investigation and remediation project 15409

corn growth in area of spill which also was area with compaction from truck movement into site for cleanup was noted in prior inspection  
user of surface for crops had reported that compacted area had been ripped as part of reclamation process prior to planting corn for 2020.corn in disturbed area had gemminated but had not continued growth and appeared stunted in comparison to ot other sections of field as  
seen in attachcd photo

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			
Crude Oil	Flow Line	>= 5 bbls			
Comment:	spill reported by initial form 19 in a timely manner. at time of inspection surface tenant and representative of KPK at area and in discussion regarding access to irrigated crop field with corn planted and growing. photos of spill area attached				
Corrective Action:	COAs to initial report are required. 45 days from date of discovery to investigate, remediate and close spill or to provide detailed site investigation plan via form 27 within 45 days of discovery			Date:	08/04/2020

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 476987 Type: SPILL OR API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697600963	spill to surface at this spot	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5180858">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5180858</a>
697600965	looking east along irrigation furrow spill followed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5180859">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5180859</a>
697600966	corn growth in area not impacted by spill/clean up	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5180860">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5180860</a>
697600967	looking west along irrigation furrow spill followed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5180861">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5180861</a>