



Location			
<b>Lease Road:</b>			
Type	Access		
comment:	2 track road in a wheat field		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Ag fence		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date
Comment:	appears to be plumbed to surface		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	sitting on pallet to be reinstalled for return to service		
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 242172 Type: WELL API Number: 123-09963 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI since 8-1-2018, Form 42 (PR) 402316866 submitted on 2-19-2020 and is approved.  
Form 42 (PR) 402316884 submitted on 2-19-2020 and is approved.  
Form 42 (PR) 402415139 submitted on 6-8-2020 and is approved.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 6/22/2020 at approximately 1045 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">UPRR 38 Pan Am E #2 at API #05-123-09963 in weld County Colorado.</p> <p>While there, I observed wellsite, SI since 8-1-2018, Form 42 (PR) 402316866 submitted on 2-19-2020 and is approved. Form 42 (PR) 402316884 submitted on 2-19-2020 and is approved. Form 42 (PR) 402415139 submitted on 6-8-2020 and is approved. During this inspection no compliance issues were observed: See attached photos. Location is dry, weather is clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	06/22/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301971	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5181118">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5181118</a>