

Inspection Photos  
Operator: BP America  
API: 067-06921  
Date: 6/19/2020



Photo 1. View of the project area from the northwestern corner facing center.





Photo 2. View of the western fill slope from the northwestern corner facing southward. Revegetation is progressing, largely with smooth brome and western wheatgrass.





Photo 3. View of bare soils in the northern cut-slope facing eastward. Bare soils in the northern project area need stabilization.





Photo 4. View of the southern project area from the well pad entrance facing westward.





Photo 5. View of the reference area, comprised of ponderosa pine woodland with a grassy understory of smooth brome and western wheatgrass, as well as gambel oaks.