

# Inspection Photos

API: 05-009-06585

Operator: SOVEREIGN OPERATING COMPANY

Inspection Date: 6/22/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-009-06585 | Date: 6/22/2020

## Inspection Photos



**Photo 1.** Facing south toward the wellsite. The area of the wellsite does not have crop growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06585 | Date: 6/22/2020

## Inspection Photos



**Photo 2.** Facing north at the wellsite. This area is approximately 50 ft. x 50 ft. which does not have adequate crop growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06585 | Date: 6/22/2020



## Inspection Photos



**Photo 3.** The soils are bare of crop growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06585 | Date: 6/22/2020

## Inspection Photos



**Photo 4.** Facing south toward the surrounding crop field which has uniform crop growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06585 | Date: 6/22/2020