

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/25/2020

Submitted Date:

06/25/2020

Document Number:

699801340

FIELD INSPECTION FORM

Loc ID 334761 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerusoilandgas.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286065	WELL	PR	05/01/2017	GW	045-12604	ENYEART 16-4 (PD16)	PR
288790	WELL	PR	02/11/2008	GW	045-13575	ENYEART 16-4BB(PD16)	PR
288793	WELL	PR	02/14/2008	GW	045-13574	ENYEART 16-5BB(PD16)	PR
288799	WELL	PR	02/08/2008	GW	045-13573	ENYEART 16-5(PD16)	PR
300667	WELL	PR	05/05/2011	GW	045-17968	ENYEART GARDNER 16-5D (PD16)	PR
300668	WELL	PR	10/07/2010	GW	045-17969	ENYEART 17-8C (PD16)	PR
300669	WELL	PR	02/01/2017	GW	045-17970	ENYEART PAVISICH 16-3C (PD16)	PR
300670	WELL	PR	05/12/2010	GW	045-17971	ENYEART 17-1C (PD 16)	PR
300671	WELL	PR	05/22/2010	GW	045-17972	ENYEART 16-4D (PD16)	PR
300672	WELL	PR	05/23/2010	GW	045-17973	ENYEART 16-4C(PD16)	PR

General Comment:

COGCC Inspection Report Summary
 On Thursday 6/25/20 at approximately 13:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at CAERUS PICEANCE LLC, ENYEART-67S95W /16NWNW Location #334761 in Garfield County Colorado. This inspection is in response to complaint #18200448946, #18200448939 and #18200448940.
 While there, I observed normal production operations. All thief hatches were closed and all valves, pipes and fittings appeared to be securely fastened, there were no odors present during this inspection.
 This is a summary of inspection report

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:			Date:
Equipment:			
Type:	Horizontal Heated Separator	# 1	corrective date
Comment:			
Corrective Action:			Date:
Type:	Gas Meter Run	# 1	
Comment:			

Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	Ignitor/Combustor
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	286065	Type:	WELL	API Number:	045-12604	Status:	PR	Insp. Status:	PR
Complaint									
Comment:	Complaint #18200448946, #18200448939 and #18200448940								
Corrective Action:								Date:	
Facility ID:	288790	Type:	WELL	API Number:	045-13575	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:								Date:	
Facility ID:	288793	Type:	WELL	API Number:	045-13574	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:								Date:	
Facility ID:	288799	Type:	WELL	API Number:	045-13573	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:								Date:	
Facility ID:	300667	Type:	WELL	API Number:	045-17968	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:								Date:	
Facility ID:	300668	Type:	WELL	API Number:	045-17969	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:								Date:	
Facility ID:	300669	Type:	WELL	API Number:	045-17970	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:								Date:	
Facility ID:	300670	Type:	WELL	API Number:	045-17971	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:								Date:	

Facility ID: 300671 Type: WELL API Number: 045-17972 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Facility ID: 300672 Type: WELL API Number: 045-17973 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Ditches	Pass					
Berms	Pass					
		Berms	Pass			
Gravel	Pass					
		Gravel	Pass			
		Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699801341	Photos for Insp. #699801340	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5183975