

Inspection Photos  
Operator: BP America  
API: 067-07777  
Date: 6/24/2020



Photo 1. View of the project area from the northwestern corner facing center.





Photo 2. View of the northern fill slope from the northeastern corner facing westward. Revegetation is largely progressing within the interim reclamation areas, largely with western wheatgrass, smooth brome, and crested wheatgrass. Although, hundreds of musk thistles observed. Many appear to be recently treated, but many untreated individuals observed.





Photo 3. View of the eastern project area facing southward.





Photos 4/5. View of musk thistles within the project area, many appear to be chemically treated (left photo) and many remain untreated (right photo)



Photo 4. View of the reference area, comprised of pinyon juniper woodland with sagebrush and blue grama understory.