

Inspection Photos  
Operator: BP America  
API: 067-07713  
Date: 6/24/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is largely progressing within the interim reclamation areas, largely with western wheatgrass, smooth brome, and crested wheatgrass.



Photo 3. View of the northern cut-slope facing northward. Little vegetation is present on slope. Stabilization measures are needed.



Photo 4. View of the reference area, comprised of pinyon juniper woodland with sagebrush and blue grama understory.