

Final Reclamation Inspection

June 22, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 329752

Inspection Document #: 697501675

Weld County, CO

NWNE Section 16 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: STATE-64N64W /16NWNE

Location ID: 329752




Photo 1. Aerial imagery taken in 2015 during active operations. This complaint is in regards to associated offsite tank battery location (red circle).



Inspection Photos

Location Name: STATE-64N64W /16NWNE

Location ID: 329752



Photo 2. Photo taken from the southeastern tank battery, facing West. Photo illustrates the Operator has performed recent final reclamation activities with the evidence of fresh mulch and germination of some desirable plant species. However, annual weedy vegetation (lambsquarter, Kochia and *Setaria sp.* (foxtail)) and some noxious weeds (Canada thistle and puncturevine) were observed.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697501675

Inspection Photos

Location Name: STATE-64N64W /16NWNE

Location ID: 329752



Photo 3. Photo taken from the southern tank battery, facing North. See comments under Photo 2.



Inspection Photos

Location Name: STATE-64N64W /16NWNE

Location ID: 329752



Photo 4. Photo taken from the central tank battery, facing East. See comments under Photo 2.



Inspection Photos

Location Name: STATE-64N64W /16NWNE

Location ID: 329752



Photo 5. Photo taken from the northwestern tank battery. Photo illustrates a List B Colorado noxious weed, Canada thistle.



Inspection Photos

Location Name: STATE-64N64W /16NWNE

Location ID: 329752



Photo 6. Photo taken from the northwestern tank battery. Photo illustrates a List C Colorado noxious weed, Puncturevine.



Inspection Photos

Location Name: STATE-64N64W /16NWNE

Location ID: 329752



Photo 7. Photo taken from the northern entrance of the tank battery. Photo illustrates unused supplies left at the entrance.



Inspection Photos

Location Name: STATE-64N64W /16NWNE

Location ID: 329752



Photo 8. Photo taken from the northern entrance of the tank battery, facing South. Photo illustrates the Operator has failed to re-install fencing.



Inspection Photos

Location Name: STATE-64N64W /16NWNE

Location ID: 329752



Photo 9. Reference photo taken east of the tank battery, facing West. Reference area (below red-dashed line) illustrates the establishment of alfalfa.

