

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/24/2020

Submitted Date:

06/26/2020

Document Number:

694500205

FIELD INSPECTION FORM

Loc ID 324625 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 53790

Name of Operator: MARKUS PRODUCTION, INC

Address: 39 FAIRWAY LANE

City: LITTLETON State: CO Zip: 80123

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
mark, brown		mark@markusproduction.com	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212172	WELL	SI	02/01/2017	OW	057-06065	STATE 1-36 1	EI

General Comment:

On 6/24/2020 COGCC Staff, Kris Neidel inspected the site of Remediation Project number 11542 and Facility 324625 at the State 1-36. Weather was 75 degrees and cloudy scattered showers. The following was observed; Well PA, wellhead was cut off and on location, area of former pit and tin horn separator has been excavated into one excavation aprox 60'x25' and was filled with water, water in excavation was muddy with no obvious sign of hydrocarbon, production equipment still present on location such as; 2; AGT's, Treater, Pumpjack, Pumpjack drive motor. Within 14 days of this document, the operator shall submit a Form 27 supplemental that presents a status update on work completed. No updates have been provided on this project since the project was created. Environmental staff discussed the supplemental Form 27 with Mark Brown on 6/26/2020, Mr Brown agreed that he submit a F27s and would include lab analytical, a discription of excavation and sample locations. See attached photos.

Inspected Facilities

Facility ID: 212172 Type: WELL API Number: 057-06065 Status: SI Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Inadequate		
Comment		Piles are sitting on pad.		
Corrective Action		Soils should be removed as a part of Rem project.		Date: 07/31/2020

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500206	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5185854