

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/25/2020

Submitted Date:

06/26/2020

Document Number:

688800746

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Murray, Richard		g.richard.murray@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Heil, John		john.heil@state.co.us	
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477070	SPILL OR RELEASE	AC	06/26/2020		-	So Ute Tribal A 5-1	EI

General Comment:

[On June 25, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Southern Ute A 5-1 Spill/Release Point ID #477070. BP, SUDOE, and Cottonwood Consulting representatives were on site during this inspection.](#)

Inspected Facilities

Facility ID: 477070 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: _____

Comment: For more information regarding this release, please refer to Spill/Release Point ID #477070.

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Date: 06/27/2020

Reportable: YES GPS: Lat 37.154650 Long -107.659174

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
<p>On June 25, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Southern Ute A 5-1 Spill/Release Point ID #477070. BP, SUDOE, and Cottonwood Consulting representatives were on site during this inspection. The release day lighted on Fee land and flowed onto Tribal land where it entered an irrigation ditch. The COGIS database lists the water transfer pipeline as a 6" fiberglass water line. An approximately 10' diameter hole partially filled with fluid had formed at the release point. Wet and stained soil leading from the release point to the irrigation ditch was observed.</p> <p>The release was reportedly discovered by a BP employee walking the ROW after losses were observed.</p> <p>The water in the irrigation ditch did not have a visible sheen. No discoloration or staining was observed along the banks or on the vegetation. Water samples were in the process of being collected during this site visit. A hand crew was beginning to shovel up impacted material from around the release area, and containment BMPs were being brought in. All access was walk in at the time this inspection was conducted.</p>	hughesjo	06/26/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800747	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5185941