

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/23/2020

Submitted Date:

06/29/2020

Document Number:

689804338**FIELD INSPECTION FORM**Loc ID: 425278 Inspector Name: Waldron, Emily On-Site Inspection: ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10396

Name of Operator: SWN PRODUCTION COMPANY LLC

Address: P.O. BOX 12359

City: SPRING State: TX Zip: 77389

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Maneotis, Karen	970-620-6099	Karen_Maneotis@swn.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
425283	WELL	PR	10/28/2013	OW	107-06243	Gnat Hill 1-29	PR

General Comment:**COGCC Inspection Report 689804338 Summary**

On Tuesday 6/23/2020 at approximately 12:25, I, Inspector Emily Waldron, conducted a field inspection at SWN Production Company LLC Gnat Hill 1-29, at 05-107-06243 in Routt County Colorado.

While there, I observed production.

During this inspection the following possible compliance issues were observed:

Stained soil at pump jack exhaust. See photo 2. Properly dispose of oily waste in accordance with 907.e and securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d by 7/13/2020.

Stained soil and debris/trash at wellhead. See photos 3-4. Comply with Rule 603.f by 9/15/2019.

Apparent spill at separator. Clean-up efforts appear to have occurred but stained soil remains. No spill report in database. See photos 6-8.

Properly dispose of oily waste in accordance with 907.e and securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d by 7/13/2020.

No calibration documentation in meter run. See photo 5. Provide calibration records or calibrate meter as required by Rule 328 within 30 days. Proof of calibration may be provided on a Field Inspection Resolution Report (FIRR) to include attached documentation.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at pump jack exhaust.		
Corrective Action:	Properly dispose of oily waste in accordance with 907.e. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	07/13/2020
Type	TRASH		
Comment:	Stained soil and debris/trash at wellhead.		
Corrective Action:	Comply with Rule 603.f.	Date:	09/05/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	
Condensate	Separator		
Comment:	Apparent spill at separator. Clean-up efforts appear to have occurred but stained soil remains. No spill report in database.		
Corrective Action:	Properly dispose of oily waste in accordance with 907.e. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 07/13/2020

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:			

Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	No calibration documentation.		
Corrective Action:	Provide calibration records or calibrate meter as required by Rule 328 and/or 329 choose appropriate rule citation) within 30 days. Proof of calibration may be provided on a Field Inspection Resolution Report (FIRR) to include attached documentation.	Date:	07/29/2020
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate			Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	425283	Type:	WELL	API Number:	107-06243	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Pumping.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689804339	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187044