

**Inspection Photos**  
**Operator: BP America**  
**API: 067-06631**  
**Date: 6/29/2020**



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the northern fill slope from the northeastern corner facing westward.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of musk thistles wilting from what appears to be herbicide treatment within the eastern project area.



Photo 5. View of Russian knapweeds blooming within the northern project area. Approximately 100 individuals observed.



Photo 6. View of the reference area, comprised of pinyon juniper woodland with sagebrush, blue grama, and penstemon in the understory.