

Inspection Photos
Operator: BP America
API: 067-06783
Date: 6/29/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern fill slope from the northwestern corner facing eastward.



Photo 3. View of herbicide treated musk thistles within the northern project area.



Photo 4. View of Russian knapweeds within the northern project area. Approximately 1000 individuals observed.



Photo 5. View of erosional headcut, approximately 3 feet wide and 2 feet deep, within the eastern stormwater diversion.



Photo 6. View of the reference area, comprised of pinyon juniper woodland with sagebrush, blue grama, and penstemon in the understory.