

KP Kauffman - COGCC Inspection Photos
Location: Nessu Consolidation OLF Release
Spill ID # 476987 Date 6/29/2020



View of failed section of fiberglass pipe and fitting installed as part of repair completed by KPK in response to reportable spill ID #470915 submitted to COGCC on 1/17/2020.



Closer view of fitting on cut end of pipe section; KPK crew informed COGCC Inspector a leak is suspected to have developed between fitting and outside wall of FG pipe. Integrity/ adhesion failure of the prior repair is suspected to have caused second reportable spill (#476987)

KP Kauffman - COGCC Inspection Photos
Location: Nesssu Consolidation OLF Release
Spill ID # 476987 Date 6/29/2020



View of excavation and NESSSU Consolidation OLF repair in process of being completed on 6/26/2020. Looking North.



Close up view of South wall of excavation at Spill ID # 476987 with flowlines exposed; cut end of a second 3" fiberglass flowline can be seen between pipe stub and shovel handle. Date 6/26/2020.

KP Kauffman - COGCC Inspection Photos
Location: Nesssu Consolidation OLF Release
Spill ID # 476987 Date 6/29/2020



Repair completed to Nesssu Consolidation OLF; a bolted clamp has been used as part of the flowline repair.

Date 6/29/2020.

View of repair completed to Nesssu Consolidation OLF; looking South. A bend can be seen in the repaired section of flowline; cut ends and repair stub section do not appear to align. Date 6/29/2020.