

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.977638,-104.537207
Comment:	Stained soil at load off line of crude tank.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Corrective action date 7/27/2020. See attached photo #5				Date: 07/27/2020

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		
Comment:	Netting on open tanks inadequate.				
Corrective Action:	Wildlife protections devices not adequate. Install or repair wildlife protection equipment per rule 324 A.a. Corrective action date 7/8/2020 See attached photo #6.				Date: 07/08/2020

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	120bbbs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 202572 Type: WELL API Number: 001-07977 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Comment: Appears to be plumbed to surface.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday June 24, 2020 at approximately 9:15am, I, Inspector Chane Finkenbinder, Conducted an on-site inspection at the Eleanor Arnold B Painted Pegasus Petroleum, at API #001-07977 in Adams County Colorado. While there, I observed a Shut in well. During this inspection the following possible compliance issues were observed: Stained soil at load off line of crude tank and at well head. Control and contain spills/releases and clean up per Rule 906.a. Corrective action date 7/27/2020. See attached photos #. 5 & 7. Netting on open tanks inadequate. Wildlife protections devices not adequate. Install or repair wildlife protection equipment per rule 324 A.a. Corrective action date 7/8/2020 See attached photo #6. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	06/25/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402431535	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5184092
700900201	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5184091